




# ICON9000

## INSTALLATION ON DOUBLE-FRONT CANTILEVER SUPPORT



### INSTALLATION RESTRICTIONS

Appliances NOT allowed to be positioned on cantilever installation: neutral surfaces 0N0PN-1N0PN-0T0PN-1T0PN, fryers 0N1FR7IX-0N1FR1EX- 0T1FR7IX-0T1FR1EX, boiling pans 14N1PD3G-14N1PI3G-14N1PI3E, automatic pasta cookers 10NCP1IA-12NCP1IA-20NCP2IA-10NCP1EA-12NCP1EA, refrigerated under counters 2NIBNC-2NIBBC, equipped uprights